

Nov. 15/10



8813 Hwy 41 South
Riverview, FL
Telephone: (813) 877-9111 - TELX52666
Fax: (813) 871-8283 ACCOUNTING

This product was produced at Riverview facility
the Production Plant.

CAR NO: SHPX264539
Deliveries: 1000647189

Material: Our / Your reference
200011 Fluorosilicic Acid /

Inspection lot 100000038891 from 08/11/2010.

Date	08/12/2010
Purchase order item/date	10025002 / 08/11/2010
Delivery item/date	1000647188 000010 / 08/16/2010
Order item/date	1233141 000010 / 08/11/2010
Customer number	5002718

45336771
Rlcshpx264538

Characteristic	Result	Unit
Chemical Analysis		
Net H2SiF6	24.85	%
P2O5	0.09	%
Lead	< 1.00	ppm
Arsenic	31.50	ppm
Physical Analysis		
Density	1.2230	
APHA	30	



8813 Hwy 41 South
Riverview, FL
Telephone: (813) 877-9111 - TELX52666
Fax: (813) 871-8283 ACCOUNTING

This product was produced at the Production Plant: - Riverview facility

CAR NO: SHPX264535
Deliveries: 1000189122

Material: Our / Your reference
200011 Fluorosilicic Acid /

Inspection lot 100000010481 from 09/05/2007

Characteristic	Result
Chemical Analysis	
Net H2SiF6	24.69
P2O5	0.28
Lead	< 1.00
Arsenic	40.75
Physical Analysis	
Density	1.2190
APHA	40



Certified to NSF/ANSI 61
Standard 101 - 1998